

**Technical Bulletin No:** XT501-S940  
**Issue Date:** June 03  
**Vehicle:** X-Type 2002-03-MY-ON  
**VIN:** C00294-D29054

## **Headlamp Washer Jet Cover Pivot Link - Change Of Specification**

### **Problem**

Service Action S940.

On vehicles fitted with headlamp power wash, there has been a high incidence of headlamp washer jet cover loss; caused by the detachment of the link that attaches the jet telescope to the washer jet cover.

### **Action**

At the next available opportunity replace the link on all 2002-03 MY X-TYPE vehicles, within the above VIN range, that are equipped with headlamp power wash.

**Note:** This Service Action covers the replacement of the link only. Should the headlamp washer jet covers be missing, please refer to Technical Bulletin: XT501-09.